



ecology and environment, inc.

101 YESLER WAY, SEATTLE, WASHINGTON, 98104, TEL. 206/624-9537

International Specialists in the Environment

MEMORANDUM

DATE: November 28, 1988

TO: John Osborn, FIT-RPO, USEPA, Region X

THRU: Jeffrey Villnov, FIT-OM, E & E, Seattle *AMJ*

FROM: Lynn Guilford, FIT-PM, E & E, Seattle *LG*

SUBJ: Site Inspection Recommendations
J.H. Baxter and Company Inc.
Arlington, Washington

REF: TDD F10-8808-17
PAN FVA0076SA

CC: Deborah Flood, HWD-SM, USEPA, Region X

The J.H. Baxter and Company Inc. facility in Arlington, Washington is a wood-treating facility with limited regulatory history. Based on the available analytical data and the potential for groundwater to be affected, additional work is recommended at this site. The work should include sampling to address the potential for groundwater contamination and the possibility that some on-site production processes (involving the cooling tower) may be impacting air quality.

LG:csr

Enclosures